Kinsmen Hall Accessibility Upgrades Project Manager: Melissa Anastacio Project Architect: BSN Architects



Existing Ramp Condition 1

- Ramp & Landing widths do not satisfy current FADS standards
- Tactile surface indicators not provided (fall hazard)





Existing Ramp Condition 2

• Entry door does not meet current FADS standards. Door requires widening to accommodate wheelchairs more comfortably





Existing Ramp Condition 3

- Entrance canopy does not provide sufficient shelter and protection from the elements.
- Canopy drains water onto stairs (slipping hazard).






Proposed Ramp Condition 1

- 1:15 maximum slope ramp as per FADS
- Increased ramp and landing widths
- Edge protection at ramps





Proposed Ramp & Landing Dimensions





Proposed Canopy and Door Widening

- Larger canopy provides enhanced protection to landing.
- Wider door provides
 965mm minimum clear
 door opening



