City of Mississauga Corporate Report



Date: January 4, 2021

- To: Chair and Members of General Committee
- From: Geoff Wright, P.Eng, MBA, Commissioner of Transportation and Works

Originator's files: MG.23.REP RT.10.Z-54

Meeting date: January 27, 2021

Subject

All-Way Stop – Copenhagen Road at Tamar Mews (Ward 9)

Recommendation

That an all-way stop control not be implemented at the intersection of Copenhagen Road at Tamar Mews, as outlined in the report from the Commissioner of Transportation and Works, dated January 4, 2021 and entitled "All-way Stop – Copenhagen Road at Tamar Mews (Ward 9)".

Background

The Transportation and Works Department has been requested by the Ward Councillor to submit a report to General Committee regarding the implementation of an all-way stop at the intersection of Copenhagen Road at Tamar Mews.

Currently, the intersection of Copenhagen Road at Tamar Mews operates as a four-leg intersection with stop controls northbound and southbound on Tamar Mews. A location map is attached as Appendix 1.

Comments

A manual turning movement count was completed to determine the need for an all-way stop control based on traffic volumes. The results are as follows:

Copenhagen Road at Tamar Mews

		<u>Warrant Value</u>
Warrant 1:	Volume for All Approaches	100%
Warrant 2:	Minor Street Volume	82%

In order for an all-way stop control to be warranted based on traffic volumes, both Warrants 1 and 2 must equal 100%. A review of the collision history at this intersection did not reveal any

9.2

9.2

2

Originators files: MG.23.REP RT.10.Z-54

reported collisions within the past three years. For an all-way stop control to be warranted based on collision frequency, at least five collisions must occur in a 12-month period, provided the collisions are of the type considered correctable by the use of an all-way stop (i.e. turning movement, angle collisions).

Therefore, an all-way stop is not warranted based on the turning movement count results and collision history.

Financial Impact

In the event that an all-way stop is required, costs associated with the sign installations can be accommodated by the 2021 Operating Budget in cost center 23978.

Conclusion

Based on the manual turning movement count results and collision history at this intersection, the Transportation and Works Department recommends against the installation of an all-way stop at the intersection of Copenhagen Road at Tamar Mews.

Attachments

Appendix 1: Location Map - All-Way Stop – Copenhagen Road at Tamar Mews (Ward 9)

Wright

Geoff Wright, P.Eng, MBA, Commissioner of Transportation and Works

Prepared by: Milan Pavlovic, Traffic Operations Technician