City of Mississauga

Corporate Report



Date: March 17, 2021

To: Chair and Members of General Committee

From: Geoff Wright, P.Eng, MBA, Commissioner of

Transportation and Works

Originator's files: MG.23.REP RT.10.Z-14

Meeting date: April 14, 2021

Subject

All-Way Stop – Edgeworth Road and Hensall Street (Ward 7)

Recommendation

That an all-way stop control not be implemented at the intersection of Edgeworth Road and Hensall Street, as outlined in the report from the Commissioner of Transportation and Works, dated March 17, 2021 and entitled "All-Way Stop – Edgeworth Road and Hensall Street (Ward 7)".

Background

The Transportation and Works Department has been requested by the Ward Councillor to submit a report to General Committee regarding the implementation of an all-way stop at the intersection of Edgeworth Road and Hensall Street.

Currently, the intersection of Edgeworth Road and Hensall Street operates as a three-leg intersection with a stop control eastbound on Edgeworth Road. A location map is attached as Appendix 1.

Comments

A manual turning movement count was completed to determine the need for an all-way stop control based on traffic volumes. The results are as follows:

Edgeworth Road and Hensall Street

		<u>warrant value</u>
Warrant 1:	Volume for All Approaches	44%
Warrant 2:	Minor Street Volume	79%

Originators files: MG.23.REP

RT.10.Z-14

In order for an all-way stop control to be warranted based on traffic volumes, both Warrants 1 and 2 must equal 100%. A review of the collision history at this intersection did not reveal any reported collisions within the past three years. For an all-way stop control to be warranted based on collision frequency, at least five collisions must occur in a 12-month period, provided the collisions are of the type considered correctable by the use of an all-way stop (i.e. turning movement, angle collisions).

Therefore, an all-way stop is not warranted based on the turning movement count results and collision history.

Financial Impact

In the event that an all-way stop is required, costs associated with the sign installations can be accommodated by the 2021 Operating Budget in cost center 23978.

Conclusion

Based on the manual turning movement count results and collision history at this intersection, the Transportation and Works Department recommends against the installation of an all-way stop at the intersection of Edgeworth Road and Hensall Street.

Attachments

ywnght

Appendix: Location Map – All-Way Stop – Edgeworth Road and Hensall Street (Ward 7)

Geoff Wright, P.Eng, MBA, Commissioner of Transportation and Works

Prepared by: Milan Pavlovic, Traffic Operations Technician