# City of Mississauga Corporate Report



Date: January 4, 2021

- To: Chair and Members of General Committee
- From: Geoff Wright, P.Eng, MBA, Commissioner of Transportation and Works

Originator's files: MG.23.REP RT.10.Z-02

Meeting date: January 27, 2021

#### Subject

All-Way Stop – Bexhill Road at Contour Drive (Ward 2)

#### Recommendation

That an all-way stop control not be implemented at the intersection of Bexhill Road at Contour Drive, as outlined in the report from the Commissioner of Transportation and Works, dated January 4, 2021 and entitled "All-way Stop – Bexhill Road at Contour Drive (Ward 2)".

#### Background

The Transportation and Works Department has been requested by the Ward Councillor to submit a report to General Committee regarding the implementation of an all-way stop at the intersection of Bexhill Road at Contour Drive.

Currently, the intersection of Bexhill Road at Contour Drive operates as a three-leg intersection with a stop control westbound on Contour Drive. A location map is attached as Appendix 1.

#### Comments

A manual turning movement count was completed to determine the need for an all-way stop control based on traffic volumes. The results are as follows:

Bexhill Road at Contour Drive

		Warrant Value
Warrant 1:	Volume for All Approaches	100%
Warrant 2:	Minor Street Volume	73%

In order for an all-way stop control to be warranted based on traffic volumes, both Warrants 1 and 2 must equal 100%. A review of the collision history at this intersection did not reveal any reported collisions within the past three years. For an all-way stop control to be warranted based on collision frequency, at least five collisions must occur in a 12-month period, provided

2

Originators files: MG.23.REP RT.10.Z-02

the collisions are of the type considered correctable by the use of an all-way stop (i.e. turning movement, angle collisions).

Therefore, an all-way stop is not warranted based on the turning movement count results and collision history.

## **Financial Impact**

In the event that an all-way stop is required, costs associated with the sign installations can be accommodated by the 2021 Operating Budget in cost center 23978.

# Conclusion

Based on the manual turning movement count results and collision history at this intersection, the Transportation and Works Department recommends against the installation of an all-way stop at the intersection of Bexhill Road at Contour Drive.

### Attachments

Appendix 1: Location Map - All-Way Stop – Bexhill Road at Contour Drive (Ward 2)

Wright

Geoff Wright, P.Eng, MBA, Commissioner of Transportation and Works

Prepared by: Milan Pavlovic, Traffic Operations Technician