Site Inspection Report

Corporate Services Office of the City Clerk



Site						医 有性毒素		是世界的 是 1000年1000年1000年1000年1000年1000年1000年100
School:		Address:						School Times 9:00 AM
Huntington Ridg	e Public	3		ngton Ridge				3:30 PM
School		N	lississau	ga, Ontario	L5R 1R6			WTS Ves No
Student Population F	French Immersion F	opulation [No. of Large B	uses	1	No. of S	Small Buses 6
486			-	No. of Student	s on the Bus	18	No. of S	Students on the Bus 14
School:		Address:						School Times AM
								PM
								WTS C Yes C No
Student Population	French Immersion	Population		No. of Large B	uses		No. of S	Small Buses
				No. of Student	s on the Bus		No. of S	Students on the Bus
Location: (Please identify the lo	cation with reference	ce or	t the Llevit	togo Hillo Do	rl. Doth @ V	Vinfield Torre	200 9 1/	Vootbourno Torroco
nearest intersection. Indicate ne	arest school and a	ddress)	t the Hern	tage Hills Pai	rk Pain @ v	vinileid Terra	ace & v	Vestbourne Terrace
Proximity to School	in front of			✓ within		260	feet/me	atres
A 11 VIII 4	III II III III OII	0		VVIIIIII		1 200	TOCUTTIC	1103
Accident History (during school times)	Yes O No	Co	omments:					
	103 () 110		tion Times			Deguasted Du	P	
Date of Inspection: 2021	03 18	Inspect	tion Time: 8:25	3:25		Requested By:	Reside	ent
			0.23 A	and the second s	PM			
Prepared By: L. Goegan				Request Fo		ent of a Scho	ol Cros	ssing Guard
L. Coogan					1 10001110		01 0100	
Observers	tigetal properties and		STATE OF THE		The same of			
		- File Nove				Ward:		
File Number:		File Nur RT.10	mber:			Ward Ward	4	
Observed By: L. Goegan			,			AM		PM ✓ AM & PM
						T AM		PM AM & PM
T. BIOWII								Parameter Communication Commun
TV. Tollall						AM	V	PM AM & PM
Observed By: S. Duffin						AM	✓	PM AM & PM
Observed By:						AM		PM AM & PM
Observed By:						AM		PM AM & PM
Site Conditions								
School Signs:	School Area	Ciano -	School	Crossing Signs	7.0	arking/Stopping	Prohibit	tion
							FIOIIIDIL	.1011
Posted Speed Limit:	40 km/hr	√ 50 k	km/hr	60 km/hr		Other:		MARKAN
Visibility of Crossing Pedestrians:	Poor	Fair		√ Good	Comme	nts:		
Sight Obstructions:	Hedges	Tree	es	Fences		sus Shelter		
Road Grade:	Newspaper B	oxes		Other (Spec		\!:		
participal de colonidado de colonidade de co	√ Flat		Protection	cline	- Francis	ecline		
Road Geometrics:	Straight		and Robinson	urved		ts: EAST		
Road Width: 31 FEET	Curb to Curb:			o. of Bike Lanes	No.	of Through Lan	ies 2	No. of Turning Lanes
Leg: NSEVW		feet/m	netres	(5)	prosper-vicusive energineer-vi-		L	The parameter was a second
Road Width: Leg: N S E W	Curb to Curb:	foot/m	netres	o. of Bike Lanes	No.	of Through Lan	ies	No. of Turning Lanes
Leg: N S E W Road Conditions:	AM: - Da			Ε.ο.	0 1		1	- International Control of the Contr
	PM: Dry		Wet Wet		low Covered			
Sidewalks:	Not Present	✓ Nor		✓ South	✓ East		West	
Route Survey:	Shopping Are		Construc	Animal	Drive	Francisco		rked Vehicle(s)
•	Transit Bus S	F.01	Underpa	_	Posterior	netres		specify): AT PARK PATH

Details		8.2	2
Weather Cond	itions: AM:	Dry Sunny ✓ Rain Snow Temperature: +1 C Other:	
	PM:	✓ Dry Sunny Rain Snow Temperature: +7 C Other:	
Type of Crossi		4 Way Intersection Widblock (i.e., not an intersection)	
Type of Contro	l:	Traffic Lights Yield Signs No Control Adequate Control	
		Stop Signs (Traffic is stopped on one street only) All Way Stop (Traffic is stopped in all direction	ıs)
Crossing Gu	ard Warrant S	Burvey	
Location: At the	ne Heritage Hil	lls Park Path @ Winfield Terrace & Westbourne Terrace	
✓ Safe Gap	Time	Safe Gap Time Calculation (if applicable): $\left(\frac{W}{3.5} + 4\right)$ 13 = sec.	
	Intersection Tur	Safe Gap Time Calculation (if applicable): $\left(\frac{W}{3.5} + 4\right)$,
Morning Inte	ervals		公务 结束
# of Peds	Time (AM)	Gaps Leg: □ N □ S □ E ✓ W	# of Gaps
	7:30 - 7:35		
and the second of the second of the second of the second	7:35 - 7:40		
	7:40 - 7:45		
	7:45 - 7:50		
	7:50 - 7:55		
	7:55 - 8:00		
	8:00 - 8:05		
	8:05 - 8:10		
	8:10 - 8:15		
Parties and the same of the sa	8:15 - 8:20		
PAGE DESCRIPTION OF THE PAGE D	8:20 - 8:25		
	8:25 - 8:30	22,22,/,100,/,30	11
	8:30 - 8:35	42,240	21
Electromatical particular of the second	8:35 - 8:40	120,148,15	21
	8:40 - 8:45	[180,32,/,40	18
/P	8:45 - 8:50	50,21,/	4
/P	8:50 - 8:55	360,35,75,62,20	39
	8:55 - 9:00		
Afternoon In	tervals		
# of	Time	Gaps	# of
Peds	(PM)	Gaps Leg: □ N □ S □ E ▼ W	Gaps
	2:30 - 2:35		
	2:35 - 2:40		
Address of the Control of the Contro	2:40 - 2:45		
Professional	2:45 - 2:50		
	2:50 - 2:55		
	2:55 - 3:00		Personal de la constant de la consta
	3:00 - 3:05		
	3:05 - 3:10		
	3:10 - 3:15		
	3:15 - 3:20		
/P	3:20 - 3:25	/,60,15,62,36	11
/P,/P	3:25 - 3:30	[65,///,15,///,32,/	8
////P,//P	3:30 - 3:35	118,22,26	12
/P	3:35 - 3:40	103,25,34,22,////	11
umidmono.com/material.com/material.com/	3:40 - 3:45	60,/,47,88,60	17
	3:45 - 3:50	1154 / 00 / 400 /// 00	14
		54,/,22,/,102,///,38	
Processing	3:50 - 3:55 3:55 - 4:00	[54, <i>I</i> ,22, <i>I</i> ,102, <i>III</i> ,38] [13,18, <i>I</i> /,36,24, <i>I</i> ,60,15]	10

Observations
Volume of Traffic (see Intersection Plan):
AM: ☐ Heavy ☐ Light ✓ Intermittent PM: ☐ Heavy ✓ Light ☐ Intermittent
Number of Crossing Pedestrians: AM: North East South West 6 PM: North East South West 10
Turning Traffic: AM: Heavy Light Intermittent PM: Heavy Light Intermittent
Traffic Behaviour
AM: Illegal U-turns Running Red Light Speeding Stopping Non-Compliance Illegal Stopping Illegal Parking Other
PM: Illegal U-turns Running Red Light Speeding Stopping Non-Compliance Illegal Stopping Illegal Parking Other
Comments/Conflicts
- ST. MATTHEW CATHOLIC ELEMENTARY SCHOOL IS CLOSED TO IN-CLASS LEARNING DUE TO COVID-19. STUDENT ENROLLMENT FOR IN-CLASS LEARNING AT HUNTINGTON RIDGE PUBLIC SCHOOL NOT AT FULL CAPACITY.
ENROLLMENT FOR IN-CLASS LEARNING AT HONTINGTON RIDGE PUBLIC SCHOOL NOT AT FULL CAPACITY.
- VERY LITTLE VEHICULAR TRAFFIC BOTH AM & PM. MOST TRAFFIC SCHOOL RELATED; DROPPING OFF STUDENTS AT THE PARK PATH TO ACCESS HUNTINGTON RIDGE PUBLIC SCHOOL. VEHICLES PARK ON WINFIELD TERRACE AND ON WESTBOURNE TERRACE TO DROP OFF AND PICKUP AM & PM.
- STOPPING COMPLIANCE GOOD WHEN STUDENTS PRESENT, POOR WHEN NO STUDENTS PRESENT.
- NO CONFLICTS OBSERVED.
- NO SIDEWALK ON THE EAST SIDE OF WESTBOURNE TERRACE. WEST SIDE THE SIDEWALK DOES NOT CONNECT TO THE SIDEWALK ON THE SOUTH SIDE OR TO THE PARK PATH LEADING TO THE REAR OF BOTH ST. MATTHEW CATHOLIC ELEMENTARY SCHOOL AND HUNTINGTON RIDGE PUBLIC SCHOOL.
Recommendations
Recommendations 1) THAT TRAFFIC SAFETY COUNCIL BE REQUESTED TO RE-INSPECT ONCE ST. MATTHEW CATHOLIC ELEMENTARY SCHOOL RETURNS TO IN-CLASS LEARNING.
1) THAT TRAFFIC SAFETY COUNCIL BE REQUESTED TO RE-INSPECT ONCE ST. MATTHEW CATHOLIC ELEMENTARY SCHOOL
1) THAT TRAFFIC SAFETY COUNCIL BE REQUESTED TO RE-INSPECT ONCE ST. MATTHEW CATHOLIC ELEMENTARY SCHOOL RETURNS TO IN-CLASS LEARNING.
1) THAT TRAFFIC SAFETY COUNCIL BE REQUESTED TO RE-INSPECT ONCE ST. MATTHEW CATHOLIC ELEMENTARY SCHOOL RETURNS TO IN-CLASS LEARNING. 2) THAT TRANSPORTATION AND WORKS BE REQUESTED TO REVIEW THE FEASIBILITY OF: A) INSTALLING A LANDING PAD ON THE SOUTH SIDE OF WINFIELD TERRACE TO ALIGN WITH THE SIDEWALK ON THE WEST
1) THAT TRAFFIC SAFETY COUNCIL BE REQUESTED TO RE-INSPECT ONCE ST. MATTHEW CATHOLIC ELEMENTARY SCHOOL RETURNS TO IN-CLASS LEARNING. 2) THAT TRANSPORTATION AND WORKS BE REQUESTED TO REVIEW THE FEASIBILITY OF: A) INSTALLING A LANDING PAD ON THE SOUTH SIDE OF WINFIELD TERRACE TO ALIGN WITH THE SIDEWALK ON THE WEST SIDE OF WESTBOURNE TERRACE.
1) THAT TRAFFIC SAFETY COUNCIL BE REQUESTED TO RE-INSPECT ONCE ST. MATTHEW CATHOLIC ELEMENTARY SCHOOL RETURNS TO IN-CLASS LEARNING. 2) THAT TRANSPORTATION AND WORKS BE REQUESTED TO REVIEW THE FEASIBILITY OF: A) INSTALLING A LANDING PAD ON THE SOUTH SIDE OF WINFIELD TERRACE TO ALIGN WITH THE SIDEWALK ON THE WEST SIDE OF WESTBOURNE TERRACE.
1) THAT TRAFFIC SAFETY COUNCIL BE REQUESTED TO RE-INSPECT ONCE ST. MATTHEW CATHOLIC ELEMENTARY SCHOOL RETURNS TO IN-CLASS LEARNING. 2) THAT TRANSPORTATION AND WORKS BE REQUESTED TO REVIEW THE FEASIBILITY OF: A) INSTALLING A LANDING PAD ON THE SOUTH SIDE OF WINFIELD TERRACE TO ALIGN WITH THE SIDEWALK ON THE WEST SIDE OF WESTBOURNE TERRACE.
1) THAT TRAFFIC SAFETY COUNCIL BE REQUESTED TO RE-INSPECT ONCE ST. MATTHEW CATHOLIC ELEMENTARY SCHOOL RETURNS TO IN-CLASS LEARNING. 2) THAT TRANSPORTATION AND WORKS BE REQUESTED TO REVIEW THE FEASIBILITY OF: A) INSTALLING A LANDING PAD ON THE SOUTH SIDE OF WINFIELD TERRACE TO ALIGN WITH THE SIDEWALK ON THE WEST SIDE OF WESTBOURNE TERRACE.
1) THAT TRAFFIC SAFETY COUNCIL BE REQUESTED TO RE-INSPECT ONCE ST. MATTHEW CATHOLIC ELEMENTARY SCHOOL RETURNS TO IN-CLASS LEARNING. 2) THAT TRANSPORTATION AND WORKS BE REQUESTED TO REVIEW THE FEASIBILITY OF: A) INSTALLING A LANDING PAD ON THE SOUTH SIDE OF WINFIELD TERRACE TO ALIGN WITH THE SIDEWALK ON THE WEST SIDE OF WESTBOURNE TERRACE.
1) THAT TRAFFIC SAFETY COUNCIL BE REQUESTED TO RE-INSPECT ONCE ST. MATTHEW CATHOLIC ELEMENTARY SCHOOL RETURNS TO IN-CLASS LEARNING. 2) THAT TRANSPORTATION AND WORKS BE REQUESTED TO REVIEW THE FEASIBILITY OF: A) INSTALLING A LANDING PAD ON THE SOUTH SIDE OF WINFIELD TERRACE TO ALIGN WITH THE SIDEWALK ON THE WEST SIDE OF WESTBOURNE TERRACE.
1) THAT TRAFFIC SAFETY COUNCIL BE REQUESTED TO RE-INSPECT ONCE ST. MATTHEW CATHOLIC ELEMENTARY SCHOOL RETURNS TO IN-CLASS LEARNING. 2) THAT TRANSPORTATION AND WORKS BE REQUESTED TO REVIEW THE FEASIBILITY OF: A) INSTALLING A LANDING PAD ON THE SOUTH SIDE OF WINFIELD TERRACE TO ALIGN WITH THE SIDEWALK ON THE WEST SIDE OF WESTBOURNE TERRACE.
1) THAT TRAFFIC SAFETY COUNCIL BE REQUESTED TO RE-INSPECT ONCE ST. MATTHEW CATHOLIC ELEMENTARY SCHOOL RETURNS TO IN-CLASS LEARNING. 2) THAT TRANSPORTATION AND WORKS BE REQUESTED TO REVIEW THE FEASIBILITY OF: A) INSTALLING A LANDING PAD ON THE SOUTH SIDE OF WINFIELD TERRACE TO ALIGN WITH THE SIDEWALK ON THE WEST SIDE OF WESTBOURNE TERRACE.