

Living Arts Center



Entry Doors Replacement

Project Reference: Civic Center doors replacement


North Entry Doors

Existing storefront system was replaced with new sliding doors at both main entrance and vestibule doors from Great Hall.

Plan & Elevations:



EXISTING ELEVATION
DOOR 1105A, 1105B, 1105C



NEW ELEVATION
DOOR 1105A

Project Reference: Civic Center doors replacement

Reference : North Entrance doors

Before & After




Living Arts Center: Entry Doors Replacement

LAC: South Entry Doors

Existing plan view:

Demo existing swing doors
at exterior and interior
vestibule doors



LAC: South Entry Doors

Existing: Main entry door views




LAC: South Entry Doors



Existing rain water leader pipe between the entry doors.

LAC: South Entry Doors



LAC: South Entry Doors

Existing vestibule view:




Demo existing ceiling, reroute rain water leader pipe and install new drywall ceiling and new lights.

Existing supply duct and grille to remain.


Existing door operator push button to be removed.

Existing Pedimat and flooring to be replaced.



LAC: South Entry Doors

New sliding doors: Main entry doors (exterior doors)




LAC: South Entry Doors

Existing: Vestibule doors




LAC: South Entry Doors

Recommended option: New vestibule sliding doors; retain existing structural column



LAC: East Entry Doors

Existing plan view:



LAC: East Entry Doors


Existing entry doors



Existing rain water leader pipe inside the aluminum panel.

LAC: East Entry Doors

New bi-part sliding doors: Entry Doors




LAC: East Entry Doors

Existing: vestibule doors and vestibule view




LAC: East Entry Doors

New bi-part sliding doors: Vestibule doors



LAC: West Entry Doors



Existing entry storefront system to be removed in its entirety & replaced with new automatic sliding doors with full breakout curtain wall system.

LAC: West Entry Doors

Existing: Entry doors view



Existing rain water
leader pipe to be
rerouted for new
sliding doors

LAC: West Entry Doors


Existing: Vestibule view



- Replace or paint existing HVAC grille. Remove any existing door operating push buttons

LAC: West Entry Doors

New bi-part sliding doors: Entry doors aligned with canopy column



LAC: West Entry Doors

New bi-part sliding doors: Entry doors

