Site Inspection Report





Site								
St. Marcellinus School	Secondary		tneypark Drive uga, ON L5W			School Times WTS Yes	AM PM s • No	
Student Population 1760 French Immersion Po		opulation 0			299	No. of Small Buses 8 No. of Students on the Bus 28		
School: Mississauga Secondary School		Address: 550 Courtneypark Drive West Mississauga, ON L5W 1L9			School Times 8:10 AM PM WTS V Yes • No			
Student Population 1086 French Immersion		Population 0 No. of Large Buses No. of Students on the Bus			11 296	•		
Location: (Please identify the lonearest intersection. Indicate n		Donway D	rive to Sombrer	o Way				
Proximity to School		√ within			1.9 km feet/metres			
Accident History (during school times)	Yes (No (Comments:						
Date of Inspection: 2021	09 16	Inspection Time: 7:40	AM P	PM	Requested By:	STOPR		
Prepared By: Peter Westbr	ook/Sheelagh Du	ıffin	Request For:	Review	Walking Rout	e-pedestrian bridge ov	er 401	
Observers								
File Number:		File Number:			Ward: Ward	5		
Observed By: P. Westbrook	(***************************************		✓ AM	☐ PM ☐ AM 8	k PM	
Observed By: D. Forde (ST	OPR)				✓ AM	□ РМ □ АМ 8	≩ PM	
Observed By: S. Duffin					✓ AM	PM AM 8	≩ PM	
Observed By:					I AM	☐ PM ☐ AM 8	≩ PM	
Observed By:					AM	☐ PM ☐ AM 8	k PM	
Observed By:					AM	PM AM 8	k PM	
Site Conditions			ne mente l'anne					
School Signs:	School Area Sig	igns School (Crossing Signs	F	Parking/Stopping	Prohibition		
Posted Speed Limit:	40 km/hr	50 km/hr	60 km/hr	П	Other:			
Visibility of Crossing Pedestrians:	Poor	Fair	 ✓ Good	Comme	ents:			
Sight Obstructions:	Hedges Newspaper Box	Trees xes	Fences Other (Specify	\$	Bus Shelter			
Road Grade:	Flat	√ In	icline		Decline bridge a	access		
Road Geometrics:						***************************************		
Road Width: Leg: N S E W	Curb to Curb:	feet/metres	lo. of Bike Lanes	1 No.	of Through Lane	No. of Turning La	nes	
Road Width: Leg: N S E W	Curb to Curb:	OTTOMORIO DE LA CONTRACTOR DE LA CONTRAC	lo. of Bike Lanes	No.	of Through Lane	No. of Turning La	nes	
Road Conditions:	AM:	☐ Wet	The second secon	Covered Covered	I loe			
Sidewalks:	Not Present	North	South	East		West		
Route Survey:	Shopping Area Transit Bus Sto	Account	\$1000000000000000000000000000000000000	Drive		Parked Vehicle(s) Other (specify):		

Details	Car Section Co.		8.1
Weather Condit	ions:		
veather Condit	AIVI.	✓ Dry ✓ Sunny Rain Snow Temperature: 17 C Other:	
Turn of Canadia	PM:	Dry Sunny Rain Snow Temperature: Other:	
Type of Crossin		4 Way Intersection Midblock (i.e., not an intersection)	
Type of Control:		Traffic Lights Yield Signs No Control Adequate Control	
		Stop Signs (Traffic is stopped on one street only) All Way Stop (Traffic is stopped in all direction	ıs)
Crossing Gua	ard Warrant S	Survey	
Location: Dony	vay Drive to S	Sombrero Way	***************************************
Safe Gap T	ime	Safe Gap Time Calculation (if applicable): / W	ment are a marine and a
g		Safe Gap Time Calculation (if applicable): $\left(\frac{W}{3.5} + 4\right)$ N/A = sec.	
		Thing traine count	
Morning Inte			THE NOTE OF
# of Peds	Time (AM)	Gaps Leg: □ N □ S □ E □ W	# of Gaps
	7:30 - 7:35		
***************************************	7:35 - 7:40		
Name and the second sec	7:40 - 7:45		
guardon sercono de la descripción de constante de constan	7:45 - 7:50		
1	7:50 - 7:55		
	7:55 - 8:00		
	8:00 - 8:05		
	8:05 - 8:10		
	8:10 - 8:15		
	8:15 - 8:20		1
Province of the control of the contr	8:20 - 8:25		
position of the same of the sa	8:25 - 8:30		
	8:30 - 8:35		
	8:35 - 8:40		***************************************
	8:40 - 8:45		
	8:45 - 8:50		
	8:50 - 8:55		
-	8:55 - 9:00		
L			L
Afternoon Int	and the state of t		
# of Peds	Time (PM)	Gaps Leg: N	# of Gaps
	2:30 - 2:35		
	2:35 - 2:40		
	2:40 - 2:45		
	2:45 - 2:50		
	2:50 - 2:55		
	2:55 - 3:00		
	3:00 - 3:05		
	3:05 - 3:10		
	3:10 - 3:15		
	3:15 - 3:20		
	3:20 - 3:25		
ALIGNAMES AND EMPORE A PROPERTY OF THE PROPERT	3:25 - 3:30		
	3:30 - 3:35		
	3:35 - 3:40		
	3:40 - 3:45		
	3:45 - 3:50		
	3:50 - 3:55		

3:55 - 4:00

Observations							
Volume of Traffic (see Intersection Plan): AM: Heavy Light Intermittent PM: Heavy Light Intermittent							
Number of Crossing Pedestrians: AM: North							
Turning Traffic: AM: Heavy Light Intermittent PM: Heavy Light Intermittent							
74m [Nearly] Light [Memment 1 m] Nearly [Light] Memment							
Traffic Behaviour							
AM: Illegal U-turns Running Red Light Speeding Stopping Non-Compliance Illegal Stopping Illegal Parking Other							
PM: Illegal U-turns Running Red Light Speeding Stopping Non-Compliance Illegal Stopping Illegal Parking Other							
Comments/Conflicts No zebra marked crosswalk or curb cuts that line up at the access to the bridge over the 401 at Donway Drive and Newcombe Drive, the S/W							
corner. As well as students crossing south to north here in the am to access the trail and bridge over the 401, some students and parents crossed north to south to access area elementary schools. Sidewalks only on the west side of Newcombe Drive.							
Trail and bridge clearly marked with lanes for pedestrians and cyclists.							
Offset gates in place at both ends of the bridge.							
Bridge well utilized by high school students.							
After crossing the bridge, south to north, students use various routes to access the schools. Some cut off and use Jazzy Mews, some use Flute Way and some use Sombrero Way.							
Trail and bridge over the 401 function well.							
Recommendations							
1) That Transportation & Works be requested to construct a curb cut and landing pad on the north side of Donway Drive to line up with the existing curb cut and landing pad on the southwest corner of Donway Drive and Newcombe Drive and that a zebra marked crosswalk be added on the west leg of the intersection aligning the southwest curb cut and landing pad with the new curb cut and landing pad on the north side of Donway Drive.							