## **Site Inspection Report**





Site								
School: Whitehorn Public	Cobool	Address:	Habana Arrania		School Times 9:00 AM			
vvnitenom Public	School	1	itehorn Avenue		3:20 PM			
		IVIISSISSAI	uga, Ontario L5V 2A9		WTS V es No			
	rench Immersion P	opulation	No. of Large Buses	3 No. of	Small Buses 4			
618		-	No. of Students on the Bus	62 No. of	Students on the Bus 13			
School:	A - I' -	Address:	1 - 1 - A		School Times 8:30 AM			
St. Raymond Cat		The same of the sa	itehorn Avenue		2:50 PM			
Elementary Scho	001	Mississat	uga, Ontario L5V 2A9		WTS Ves No			
	French Immersion	Population	No. of Large Buses	1 No. of	Small Buses 1			
310			No. of Students on the Bus	13 No. of	Students on the Bus 3			
Location: (Please identify the loc	Location: (Please identify the location with reference or Whitehorn Avenue & Duval Drive + @ Exit Driveway of Whitehorn PS							
nearest intersection. Indicate ne	arest school and a	ddress) vvnitenom						
Proximity to School	in front of		within White	hoth 90/250 feet/me	t. Raymond CES			
Accident History	1	Comments:	100					
(during school times)	Yes No	~~						
Date of Inspection:		Inspection Time:		Requested By:				
2023	03 08		AM 3:00 PM	Paren	t & The Principal of PS			
Prepared By:			Request For:					
P. Westbrook	/ L. Goegan			the Crosswalk/ Plac	ing a Second Guard			
Observers								
File Number:		File Number:		Ward:				
RT.10		RT.10	* 2* *	Ward 6				
Observed By: R. Crocker				AM	PM AM & PM			
Observed By: R. Maximo				✓ AM	PM AM & PM			
Observed By: P. Westbrook				✓ AM	PM AM & PM			
Observed By: L. Goegan				AM V	PM AM & PM			
Observed By: S. Duffin				AM	PM AM & PM			
Observed By:								
3555(164 5).				AM	PM AM & PM			
Site Conditions	and these seconds							
School Signs:	School Area	Signs School	Crossing Signs	Parking/Stopping Prohibi	tion			
Posted Speed Limit:	print	and the second s			CHOTT			
Visibility of Crossing	40 km/hr	50 km/hr	parame	Other: 30 KM/HR				
Pedestrians:	Poor	Fair	✓ Good Comm					
Sight Obstructions:	Hedges Newspaper B	Trees	Fences Other (Specify):	Bus Shelter				
Road Grade:	Flat		Production of the Control of the Con	Decline				
Road Geometrics:	✓ Straight		Curved Comme	nts:				
Road Width: Whitehorn Ave.	Curb to Curb:			o. of Through Lanes	No. of Turning Lanes			
Leg: N S E W		36 feet/metres	2	2	1.5. or running caries			
Road Width:	Curb to Curb:		No. of Bike Lanes No.	o. of Through Lanes	No. of Turning Lanes			
Leg: N S E W		feet/metres						
Road Conditions:	AM: Dry		Snow Covered	Ice				
Sidewalks:	PM: V Dry		Snow Covered	Ice				
Route Survey:	Not Present Shopping Are	North	South Eas		rked Vehicle(s)			
Route Survey: Shopping Area Construction Driveway - School Parked Vehicle(s)  Transit Bus Stop Underpass Within feet/metres Other (specify):								

Details			9.2					
Weather Conditi	ons: AM:	✓ Dry     ✓ Sunny     Rain     Snow     Temperature: -3 C     Other:       ✓ Dry     ✓ Sunny     Rain     Snow     Temperature: +3 C     Other:						
Type of Crossing								
Time of Control								
Type of Control:		Traffic Lights Yield Signs ✓ No Control Adequate Control  Stop Signs (Traffic is stopped on one street only)  All Way Stop (Traffic is stopped in all direction)	ns)					
Crossing Gua	rd Warrant S	urvev						
Location:		& Duval Drive + @ Exit Driveway of Whitehorn PS						
✓ Safe Gap Ti	ime	Safe Gap Time Calculation (if applicable): / W + 4	1000 0000 000 000 000 000 000 000 000 0					
		Safe Gap Time Calculation (if applicable): $\left(\frac{W}{3.5} + 4\right)$	<b>&gt;.</b>					
Morning Intervals								
# of	Time	Gaps Leg: □ N □ S □ E □ W	# of					
Peds	(AM)	Leg: NSEW	Gaps					
	7:30 - 7:35							
Lautenstein och Anti-vaterantinen ovorscatten.	7:35 - 7:40	MIDBLOCK						
L	7:40 - 7:45							
	7:45 - 7:50							
	7:50 - 7:55							
Authoritis ration and on Principality in Chicago	7:55 - 8:00		L					
Later to the discensional Assistance	8:00 - 8:05		9					
	8:05 - 8:10	[////////,14,//,21,34,/.28,17,/////,22,//,17						
	8:10 - 8:15	//////,30,/////,16,////////,21,//////						
11	8:15 - 8:20	[//,14,//////////,21,////,17,//////////						
//P,/P,//	8:20 - 8:25							
	8:25 - 8:30	14,///////////,30,/,16,17,//////////						
	8:30 - 8:35	[///////,26,/,25,//,19,//,41,////////,18,/,26,17						
	8:35 - 8:40	[//,43,//,24,/,35,//////,19,//,21,/,19,///						
/P	8:40 - 8:45	[///,20,23,////////,14,/,18,15,15,/,14,16						
6P	8:45 - 8:50	24,/////,24,///////,27,31,//,22,/,23,///////						
26P,7	8:50 - 8:55	/,19,/,50,/////,39,/////////////////////////////	8					
18P,2	8:55 - 9:00	29,///,26,///////,42,//,24,/////,28,//////,21						
Afternoon Int	ervals							
# of Peds	Time (PM)	Gaps           Leg:         N						
	2:30 - 2:35							
ALLE STATE OF THE	2:35 - 2:40	MIDBLOCK	Lancon Marian Constitution of the Constitution					
	2:40 - 2:45							
	2:45 - 2:50							
	2:50 - 2:55		TANK AND AND AND AND A STATE OF THE STATE OF					
	2:55 - 3:00							
/P,//,4P	3:00 - 3:05							
//,/P	3:05 - 3:10	[//,14,////,22,////////,14,/////,14,//						
Annual An	3:10 - 3:15	[/,38,20,///,28,/,20,///,22,///,30,/,32,//,22,/////						
	3:15 - 3:20	[//,25,17,////,22,49,////,14,//,30,/,64,////						
4P,30	3:20 - 3:25	25,/,19,///,34,///,15,130,26,//////						
21,6P,//	3:25 - 3:30	38,///,35,////////,62,//////,80,////,30,/////////////////////	15					
///P,//P	3:30 - 3:35	[//////,20,/,19,///,19,//////,17,//						
///P	3:35 - 3:40	24,///,17,///,27,/////,14,15,40,15,/,14,///,15,/						
	3:40 - 3:45	28,/,77,/,16,40,/,50,/,24,/,26,///						
	3:45 - 3:50	58,18,///,28,//,21,24,16,27,//////						
	3:50 - 3:55		12					
	3:55 - 4:00							
A a regular region of a service standard strong	0.00 - 4.00		Laurencentenancement					

Observations	
Volume of Traffic (see Intersection Plan):  AM: Heavy Light ✓ Intermittent PM: Heavy Light ✓ Intermittent	
Number of Crossing Pedestrians:	
AM: North 67 East South West PM: North 81 East South West Turning Traffic:	
AM: Heavy Light Intermittent PM: Heavy Light Intermit	tent
Traffic Behaviour	
AM: Illegal U-turns Running Red Light Speeding Stopping Non-Compliance Illegal Stopping Illegal Parking C	Other
PM: Illegal U-turns Running Red Light Speeding Stopping Non-Compliance Illegal Stopping Illegal Parking C	Other
Comments/Conflicts	
RE: REQUEST FOR THE SCHOOL CROSSWALK TO BE MOVED NORTH TO THE ALL WAY STOP AT WHITEHORN AVE. & DUV	/AL DR.
- AM - 9 STUDENTS COMING FROM SOUTH CROSSED WITH CROSSING GUARD, 58 FROM NORTH OF THE CROSSWALK CF WITH THE CROSSING GUARD WOULD NOT ACCOMMODATE STUDENTS CROSSING FROM SOUTH OF THE SCHOOL.	ROSSED
- GAPS IN AM 8:45 - 9:00 CREATED BY THE CROSSING GUARD CROSSING STUDENTS. TRAFFIC STEADY BOTH AM & PM.	
- PM - 9 STUDENTS CROSSING TO GO SOUTH CROSSED WITH CROSSING GUARD - 72 CROSSED TO PROCEED NORTH.	
- 1 U-TURN OBSERVED PM. TRAFFIC ORDERLY MANY WALKERS AT WHITEHORN PS BOTH AM & PM.	
- PARKING ENFORCEMENT ATTENDED PM - ASKED ILLEGALLY PARKED VEHICLE TO MOVE.	
- SOME SPEEDING OBSERVED ONCE CONGESTION AT ENTRY AND DISMISSAL EASED CROSSWALK FUNCTIONS WELL. TRAFFIC BACKED UP BRIEFLY AT SCHOOL DISMISSAL.	
Recommendations	
1) THAT THE SCHOOL CROSSWALK REMAIN AT ITS PRESENT LOCATION JUST NORTH OF WHITEHORN PUBLIC SCHOOL EXIT DRIVEWAY TO ACCOMMODATE STUDENTS ACCESSING THE SCHOOL FROM BOTH SOUTH AND NORTH OF THE CROSSWALK.	
2) THAT THE REQUEST FOR A SECOND CROSSING GUARD AT WHITEHORN PUBLIC SCHOOL EXIT DRIVEWAY BE DENIED ONE CROSSING GUARD FUNCTIONS WELL ON THIS TWO LANE ROAD AND THE WARRANTS ARE NOT MET FOR THE IMPLEMENTATION OF A SECOND CROSSING GUARD.	AS
3) THAT TRANSPORTATION AND WORKS ROAD SAFETY BE REQUESTED TO REVIEW THE FEASIBILITY OF INSTALLING A RAISED CROSSWALK AT THE EXISTING SCHOOL CROSSWALK JUST NORTH OF THE WHITEHORN PUBLIC SCHOOL EXI DRIVEWAY. THE INSTALLATION OF SPEED BUMPS ON WHITEHORN AVENUE IN THE VICINITY OF WHITEHORN PUBLIC SCHOOL AND ST. RAYMOND CATHOLIC ELEMENTARY SCHOOL BETWEEN DUVAL DRIVE AND PICKWICK DRIVE.	Т
4) THAT THE PRINCIPAL AND STAFF OF WHITEHORN PUBLIC SCHOOL BE COMMENDED FOR ENCOURAGING WALKING TO SCHOOL AND CONTINUING TO PROMOTE ACTIVE TRANSPORTATION.	)
	to the second se
	About
	Acceptance of the second
	and control of the control of