

# Site Inspection Report

<b>Site</b>	
School #1 <b>Chris Hadfield Public School</b>	Address <b>465 Fairview Road West Mississauga, Ontario L5B 3W7</b>
Student Population <b>550</b>	French Immersion Population
No. of Large Buses <b>6</b>	No. of Small Buses <b>3</b>
No. of Students on the Bus <b>308</b>	No. of Students on the Bus <b>14</b>
School #2	Address
Student Population	French Immersion Population
No. of Large Buses	No. of Small Buses
No. of Students on the Bus	No. of Students on the Bus
Location: (Please identify the location with reference to nearest intersection. Indicate nearest school and address) <b>In front of school @ 465 Fairview Road West</b>	
Proximity to School	Name of School #1 <b>Chris Hadfield Public School</b>
	Name of School #2
Accident History (during school times)	Comments:
Date of Inspection <b>January 12, 2023</b>	Inspection Time AM <b>8:30</b> to <b>9:00</b> PM <b>3:20</b> to <b>3:50</b>
Requested By <b>Parent</b>	
Prepared By <b>P. Westbrook / A. Alvi</b>	Request For <b>Implementation of a School Crossing Guard / Safety Measures</b>

## Observers

File Number <b>RT.10</b>	File Number <b>RT.10</b>	Ward <b>7</b>
Observed By	AM	PM
<b>P. WESTBROOK</b>	<input checked="" type="checkbox"/>	
<b>R. MAXIMO</b>	<input checked="" type="checkbox"/>	
<b>A. ALVI</b>		<input checked="" type="checkbox"/>
<b>D. MARCOTTE (PDSB-MAINTENANCE)</b>	<input checked="" type="checkbox"/>	
<b>S. DUFFIN</b>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
Observed By	AM	PM
<b>T. COULSON</b>		<input checked="" type="checkbox"/>

## Site Conditions

School Signs:	<input checked="" type="checkbox"/> School Area Signs	<input type="checkbox"/> School Crossing Signs	<input checked="" type="checkbox"/> Parking/Stopping Prohibition	<input checked="" type="checkbox"/> No U-turn Sign
Posted Speed Limit:	<input checked="" type="checkbox"/> 30 km/hr	<input type="checkbox"/> 40 km/hr	<input type="checkbox"/> 50 km/hr	<input type="checkbox"/> 60 km/hr
Visibility of Crossing Pedestrians:	<input type="checkbox"/> Poor	<input type="checkbox"/> Fair	<input checked="" type="checkbox"/> Good	Comments:
Sight Obstructions:	<input type="checkbox"/> Hedges	<input type="checkbox"/> Trees	<input type="checkbox"/> Fences	<input type="checkbox"/> Bus Shelter
Road Grade:	<input checked="" type="checkbox"/> Flat	<input type="checkbox"/> Incline	<input type="checkbox"/> Decline	
Road Geometrics:	<input checked="" type="checkbox"/> Straight	<input type="checkbox"/> Curved	Comments:	
Road Width: <b>Fairview Rd. West</b>	Curb to Curb: <b>32</b>	No. of Bike Lanes	No. of Through Lanes <b>2</b>	No. of Turning Lanes
Leg: <input type="checkbox"/> N <input type="checkbox"/> S <input checked="" type="checkbox"/> E <input type="checkbox"/> W	feet/metres			
Road Width: <b>Luzon Crescent</b>	Curb to Curb:	No. of Bike Lanes	No. of Through Lanes <b>2</b>	No. of Turning Lanes
Leg: <input type="checkbox"/> N <input type="checkbox"/> S <input type="checkbox"/> E <input type="checkbox"/> W	feet/metres			
Road Conditions:	AM: <input type="checkbox"/> Dry	<input checked="" type="checkbox"/> Wet	<input type="checkbox"/> Snow Covered	<input type="checkbox"/> Ice
Sidewalks:	PM: <input type="checkbox"/> Dry	<input checked="" type="checkbox"/> Wet	<input type="checkbox"/> Snow Covered	<input type="checkbox"/> Ice
Route Survey:	<input type="checkbox"/> Not Present	<input checked="" type="checkbox"/> North	<input checked="" type="checkbox"/> South	<input checked="" type="checkbox"/> East
Within	<input type="checkbox"/> Shopping Area	<input type="checkbox"/> Construction	<input type="checkbox"/> Driveway	<input type="checkbox"/> Parked Vehicle(s)
feet/metres	<input checked="" type="checkbox"/> Transit Bus Stop	<input type="checkbox"/> Underpass	Other (specify):	
Traffic Calming:	<input type="checkbox"/> Speed Bumps	<input type="checkbox"/> Speed Cameras	<input type="checkbox"/> Other	

**Details**

Weather Conditions: **AM:**  Dry  Sunny  Rain  Snow Temperature: **+ 2 C** Other: **Foggy**  
**PM:**  Dry  Sunny  Rain  Snow Temperature: **+ 4 C** Other: **Foggy & Misty Rain**

Type of Crossing:  4 Way Intersection  3 Way Intersection  Midblock (i.e., not an intersection)

Type of Control:  Traffic Lights  Yield Signs  Pedestrian Crossover  No Control  
 Stop Signs (Traffic is stopped on one street only)  All Way Stop (Traffic is stopped in all directions)

**Crossing Guard Warrant Survey**

Location: **In front of school @ 465 Fairview Road West**

Safe Gap Time Safe Gap Time Calculation (if applicable):  $\left(\frac{W}{3.5} + 4\right) = \text{sec. } 13$   
 Signalized Intersection Turning Traffic Count (width figure measured in feet)

**Morning Intervals**

# of Peds	Time (AM)	Gaps Leg: <input type="checkbox"/> N <input type="checkbox"/> S <input checked="" type="checkbox"/> E <input type="checkbox"/> W	# of Gaps
	<Drop downs>		
	8:35 - 8:40	/,68,105,/,17,40	17
	8:40 - 8:45	51,/,22,/,42,23,////////,18,18	10
/P,/P,/P,/P	8:45 - 8:50	25,/,19,24,////,71,////,14,////////	9
/P,///P,/P,/P	8:50 - 8:55	32,////////,21,///,18,///,16,////////,23,20,////////	7
/	8:55 - 9:00	///,49,/,18,////////,15,/,20,18,/,22,22,////	9

**Afternoon Intervals**

# of Peds	Time (PM)	Gaps Leg: <input type="checkbox"/> N <input type="checkbox"/> S <input checked="" type="checkbox"/> E <input type="checkbox"/> W	# of Gaps
	<Drop downs>		
/P,///P,///	3:20 - 3:25	18,/,68,///,25,////////	7
/P,///P	3:25 - 3:30	////////,15,////////,13,////////,15,///,21,////////	4
	3:30 - 3:35	///,22,////,37,/,30,/,28,70,/,13,47,///	16
	3:35 - 3:40	///,75,///,31,/,28,/,15,////	10
	3:40 - 3:45	32,28,35,37,16,///,22,/,14,/,25,60	16

**Observations**

Volume of Traffic:	<b>AM:</b> <input type="checkbox"/> Heavy <input type="checkbox"/> Intermittent <input checked="" type="checkbox"/> Light	<b>PM:</b> <input type="checkbox"/> Heavy <input type="checkbox"/> Intermittent <input checked="" type="checkbox"/> Light
Number of Crossing Pedestrians:	<b>AM:</b> North East <b>11</b> South West	<b>PM:</b> North East <b>8</b> South West
Turning Traffic:	<b>AM:</b> <input type="checkbox"/> Heavy <input type="checkbox"/> Intermittent <input type="checkbox"/> Light	<b>PM:</b> <input type="checkbox"/> Heavy <input type="checkbox"/> Intermittent <input type="checkbox"/> Light

**Traffic Behaviour** (Comment or Recommendation Required)

<b>AM:</b> <input type="checkbox"/> Illegal U-turn <input type="checkbox"/> Running Red Light <input type="checkbox"/> Speeding <input type="checkbox"/> Stopping Non-Compliance <input type="checkbox"/> Illegal Stopping <input type="checkbox"/> Illegal Parking <input type="checkbox"/> Other
<b>PM:</b> <input type="checkbox"/> Illegal U-turn <input type="checkbox"/> Running Red Light <input type="checkbox"/> Speeding <input type="checkbox"/> Stopping Non-Compliance <input type="checkbox"/> Illegal Stopping <input type="checkbox"/> Illegal Parking <input type="checkbox"/> Other

**Comments/Conflicts** Indicate the corresponding number(s) as well as additional comment(s)

- ALL BUT ONE OLDER STUDENT CROSSED WITH A PARENT.
- KISS AND RIDE RAN SMOOTHLY - STAFF PARTICIPATION AMPLE UNTIL STAFF LEFT AT BELL TIME AND MANY LATECOMERS STOPPED RANDOMLY IN KISS AND RIDE CAUSING SOME CHAOS.
- NO CONFLICTS OBSERVED AM & PM.
- INTERSECTION FUNCTIONS WELL AM & PM.
- STUDENTS CROSSED CONFIDENTLY AM & PM.
- ALL SIGNAGE IN PLACE ON FAIRVIEW ROAD WEST IN THE SCHOOL ZONE.
- TURNING TRAFFIC COURTEOUS TO CROSSING PEDESTRIANS AM & PM.

**Recommendations** Indicate the corresponding number(s) as well as location and/or school.

- 1) THAT THE WARRANTS HAVE NOT BEEN MET FOR THE PLACEMENT OF A SCHOOL CROSSING GUARD AT FAIRVIEW ROAD WEST AND LUZON CRESCENT. NUMEROUS SAFE GAPS IN TRAFFIC FOR STUDENTS TO CROSS THE ROAD.
- 2) THAT TRANSPORTATION AND WORKS BE REQUESTED TO PAINT ZEBRA MARKINGS ON THE EAST LEG OF THE INTERSECTION OF FAIRVIEW ROAD WEST AND LUZON CRESCENT.