Site Inspection Report





Site											
Mentor College			0 Fores /lississa	uga, C	N L5G				School Ti	3:1 ○ Yes	
Student Population 1400	Prench Immersion Population No. of Large Buses No. of Students on the Bu						26 550		Small Buse Students or	1	
School: Forest Avenue Public School Address: 20 Forest Avenu Mississauga, Ol				1K7		000000000000000000000000000000000000000	School Ti	9:0 3:2 C Yes	esperiore contraction of the con		
Student Population 191 French Immersion Population No. of Large Buses No. of Students on the Bu						126		Small Buse Students or		1	
Location: (Please identify the location with reference or nearest intersection. Indicate nearest school and address) Forest Avenue & Cayuga Avenue											
Proximity to School	Proximity to School in front of within MENTOR 350/750 FEREST AVENUE COLLEGE 350/750 feet/metres PS							IE			
Accident History (during school times) Yes No											
Date of Inspection: 2022	10 18	Inspec	8:30	AM	3:20	PM	Requested I	Parer	nt		
Prepared By: P. Westbrook / T.J. Cieciura Request For: Implementation of a School Crossing Guard							***************************************				
Observers		A CHAR									
File Number: RT.10		File Nu RT.10	mber:			*	Ward: Wa	ard 1			
Observed By: T.J. CIECIURA	4						MA AM		PM J	✓ AM & I	PM
Observed By: S. THOMSON	J	The second of th					П АМ		PM	AM & F	PM
Observed By: R. MAXIMO AM & PM AM & PM					PM						
Observed By: P. WESTBRO	OK						☐ AM		PM	✓ AM & F	PM
Observed By: S. DUFFIN							I AM		PM	✓ AM & F	PM
Observed By:							AM		PM	AM & F	PM
Site Conditions	THE STATE OF THE PARTY.		The state of	12 11		CHEEK W	W.				
School Signs:	School Area	Signs	School	Crossing	Signs	[√ F	Parking/Stopp	oing Prohib	ition		
Posted Speed Limit:	√ 40 km/hr	50	km/hr	60	km/hr		Other:				
Visibility of Crossing	Poor	Fai	r	√ Go	od	Comme	ents:			***************************************	
Pedestrians: Sight Obstructions:	Hedges Newspaper	Tre	es	☐ Fe	nces her (Speci	\$	Bus Shelter				
Road Grade:	✓ Flat			ncline			Decline			3000000	-
Road Geometrics:	√ Straight			Curved		Commen	nts:				
Road Width: 34 FEET Leg: N 7 S E W Road Width: Leg: N S E W	Curb to Curb:		metres		ke Lanes		of Through	2		urning Lane	
Road Conditions:	AM: Z D	ry [₩et Wet		Name and American	ow Covered		Ice Ice			*
Sidewalks:	Not Present	-		Bushama	outh	▼ East	t [✓ West			
Route Survey:	Shopping Ar Transit Bus		Constr Underp		Vithin	Drive	way netres	* 0,000	rked Vehicl (specify):	e(s)	

Details			9.12.
Weather Cond	MIVI.	✓ Dry Sunny Rain Snow Temperature: 4 C Other:	CDAIN
Type of Cross	PM: ing:	Dry Sunny ✓ Rain Snow Temperature: 7 C Other: SPRINKLIN 4 Way Intersection ✓ 3 Way Intersection Midblock (i.e., not an intersection)	GRAIN
Type of Contro	ol:	Traffic Lights Yield Signs No Control Adequate Control	
,		Stop Signs (Traffic is stopped on one street only) All Way Stop (Traffic is stopped in all directions)	ns)
Crossing G	uard Warrant	Survey	
Location:		Cayuga Avenue	
	Maria Cara Cara Cara Cara Cara Cara Cara		and the freedom and the production of
✓ Safe Gap		Safe Gap Time Calculation (if applicable): $\left(\frac{W}{3.5} + 4\right)$	3 .
Signalized	Intersection Tu	rning Traffic Count	
Morning Int	ervals		
# of Peds	Time (AM)	Gaps Leg: N ✓S E W	# of Gaps
	7:30 - 7:35		
	7:35 - 7:40		
	7:40 - 7:45		
	7:45 - 7:50		
	7:50 - 7:55		
	7:55 - 8:00		Ş
	8:00 - 8:05		g
loon on the second	8:05 - 8:10		
	8:10 - 8:15		
	8:15 - 8:20 8:20 - 8:25		
	8:25 - 8:30		
P*************************************	8:30 - 8:35	25,70,/,22,55,////	10
1 /	8:35 - 8:40	50,25,7,20,75,20,17,20,35,40	16
	8:40 - 8:45	65,//,28,///,70,/,30,25	14
1 /P	8:45 - 8:50	15,35,15,60,75,/,35,80	20
	8:50 - 8:55	135,//,15,//	10
	8:55 - 9:00	70,18,7,90,120	20
Afternoon Ir	ntervals		
# of Peds	Time (PM)	Gaps Leg: □N ✓S □E □W	# of Gaps
	2:30 - 2:35		
	2:35 - 2:40		
	2:40 - 2:45	Assessment and the second of t	
	2:45 - 2:50		
	2:50 - 2:55		
	2:55 - 3:00		
200000000000000000000000000000000000000	3:00 - 3:05		
<u></u>	3:05 - 3:10		
	3:10 - 3:15		
	3:15 - 3:20	24 420 26 22 25 /	1 12
//	3:20 - 3:25 3:25 - 3:30	24,130,26,23,25,/ 38,/,30,//,15,26,/,100	13
//P	3:30 - 3:35	30,//,60,//,40,//	8
	3:35 - 3:40	55,110	10
1	3:40 - 3:45	660	47
	3:45 - 3:50		
	3:50 - 3:55		
	3:55 - 4:00		Possession 1
1		A support of the contract of t	200000000000000000000000000000000000000

Observations	
Volume of Traffic (see Intersection Plan): AM:	✓ Light Intermittent
Number of Crossing Pedestrians:	ast South 4 West
Turning Traffic: AM: Heavy Light Intermittent PM: Heavy	Light Intermittent
AM. Friedry Edgit Fillermident Fill. Friedry	Eight Emittemation
Traffic Behaviour	
AM: Illegal U-turns Running Red Light Speeding Stopping Non-Compliance Illegal St	opping Illegal Parking Other
PM: Illegal U-turns Running Red Light Speeding Stopping Non-Compliance Illegal St	opping Illegal Parking Other
Comments/Conflicts	THE ADEA OF MENTOD COLLEGE
- FROM 3:10 PM ON, MENTOR PARENTS PARK LEGALLY OR ILLEGALLY ON EVERY STREET IN MOST STUDENTS WALK TO PARENTS VEHICLES. NOWHERE ELSE TO PARK. ALMOST ALL M LIVE TOO FAR FROM THE SCHOOL TO WALK.	ENTOR COLLEGE STUDENTS
- NO CONFLICTS OBSERVED.	
- FEW WALKERS FROM FOREST AVENUE PUBLIC SCHOOL. NO PROBLEMS CROSSING.	
	5
Recommendations	
1) THAT THE WARRANTS HAVE NOT BEEN MET FOR THE IMPLEMENTATION OF A SCHOOL CROINTERSECTION OF FOREST AVENUE AND CAYUGA AVENUE. MANY SAFE GAPS IN TRAFFIC ROAD. MANY PARKED/STOPPED VEHICLES DO NOT IMPACT PEDESTRIANS ON THE SIDEWA	FOR STUDENTS TO CROSS THE
	4
	,
	¥
	*
	on and a second