

Site Inspection Report

Site	
School #1 McBride Public School	Address 974 McBride Avenue Mississauga, Ontario L5C 1L6
Student Population 327	School Times AM 8:45 PM 3:05 WTS Yes <input checked="" type="checkbox"/> No
French Immersion Population	No. of Large Buses 2 No. of Students on the Bus 108
No. of Small Buses 4 No. of Students on the Bus 10	
School #2	Address
School Times AM PM	WTS Yes No
Student Population	French Immersion Population
No. of Large Buses	No. of Small Buses
No. of Students on the Bus	No. of Students on the Bus
Location: (Please identify the location with reference to nearest intersection. Indicate nearest school and address) McBride Avenue and Grechen Road	
Proximity to School	Name of School #1 McBride Public School in front of <u>within</u> 220 feet/metres
	Name of School #2 in front of <u>within</u> feet/metres
Accident History (during school times) Yes <input type="checkbox"/> No <input type="checkbox"/>	Comments:
Date of Inspection May 09, 2023	Inspection Time AM 8:15 to 8:45 PM 3:05 to 3:35
Requested By Resident	
Prepared By M. ROQUE / P. WESTBROOK	Request For Implementation of a School Crossing Guard

Observers					
File Number RT.10	File Number RT.10	Ward 6			
Observed By	AM	PM	Observed By	AM	PM
M. ROQUE	<input checked="" type="checkbox"/>				
B. PARIC		<input checked="" type="checkbox"/>			
S. DUFFIN	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>			
P. WESTBROOK		<input checked="" type="checkbox"/>			

Site Conditions					
School Signs:	<input checked="" type="checkbox"/> School Area Signs	<input type="checkbox"/> School Crossing Signs	<input type="checkbox"/> Parking/Stopping Prohibition	<input type="checkbox"/> No U-turn Sign	
Posted Speed Limit:	<input checked="" type="checkbox"/> 30 km/hr	<input type="checkbox"/> 40 km/hr	<input type="checkbox"/> 50 km/hr	<input type="checkbox"/> 60 km/hr	<input type="checkbox"/> Other:
Visibility of Crossing Pedestrians:	<input type="checkbox"/> Poor	<input type="checkbox"/> Fair	<input checked="" type="checkbox"/> Good	Comments:	
Sight Obstructions:	<input type="checkbox"/> Hedges	<input type="checkbox"/> Trees	<input type="checkbox"/> Fences	<input type="checkbox"/> Bus Shelter	
	<input type="checkbox"/> Newspaper Boxes	<input type="checkbox"/> Other (Specify):			
Road Grade:	<input checked="" type="checkbox"/> Flat	<input type="checkbox"/> Incline	<input type="checkbox"/> Decline		
Road Geometrics:	<input checked="" type="checkbox"/> Straight	<input type="checkbox"/> Curved	Comments:		
Road Width:	Curb to Curb: 33 feet	No. of Bike Lanes	No. of Through Lanes 2	No. of Turning Lanes	
Leg: <input type="checkbox"/> N <input type="checkbox"/> S <input type="checkbox"/> E <input checked="" type="checkbox"/> W					
Road Width:	Curb to Curb:	No. of Bike Lanes	No. of Through Lanes	No. of Turning Lanes	
Leg: <input type="checkbox"/> N <input type="checkbox"/> S <input type="checkbox"/> E <input type="checkbox"/> W					
Road Conditions:	AM: <input checked="" type="checkbox"/> Dry	<input type="checkbox"/> Wet	<input type="checkbox"/> Snow Covered	<input type="checkbox"/> Ice	
	PM: <input checked="" type="checkbox"/> Dry	<input type="checkbox"/> Wet	<input type="checkbox"/> Snow Covered	<input type="checkbox"/> Ice	
Sidewalks:	<input type="checkbox"/> Not Present	<input checked="" type="checkbox"/> North	<input checked="" type="checkbox"/> South	<input checked="" type="checkbox"/> East	<input checked="" type="checkbox"/> West
Route Survey:	<input type="checkbox"/> Shopping Area	<input type="checkbox"/> Construction	<input checked="" type="checkbox"/> Driveway of school	<input type="checkbox"/> Parked Vehicle(s)	
Within feet/metres	<input checked="" type="checkbox"/> Transit Bus Stop	<input type="checkbox"/> Underpass	Other (specify):		
Traffic Calming:	<input type="checkbox"/> Speed Bumps	<input type="checkbox"/> Speed Cameras	<input checked="" type="checkbox"/> Other - Edge Lines on McBride Avenue		

Details

Weather Conditions: AM: Dry Sunny Rain Snow Temperature: 9 C Other: PARTLY CLOUDY
 PM: Dry Sunny Rain Snow Temperature: 17 C Other: PARTLY CLOUDY

Type of Crossing: 4 Way Intersection 3 Way Intersection Midblock (i.e., not an intersection)

Type of Control: Traffic Lights Yield Signs Pedestrian Crossover No Control
 Grechen Road Stop Signs (Traffic is stopped on one street only) All Way Stop (Traffic is stopped in all directions)

Crossing Guard Warrant Survey

Location: McBride Avenue and Grechen Road

Safe Gap Time Safe Gap Time Calculation (If applicable): $(\frac{W}{3.5} + 4) 13 = \text{sec.}$
 Signalized Intersection Turning Traffic Count (width figure measured in feet)

Morning Intervals

# of Peds	Time (AM)	Gaps Leg: <input type="checkbox"/> N <input type="checkbox"/> S <input checked="" type="checkbox"/> E <input type="checkbox"/> W	# of Gaps
	<Drop downs>		
	8:15 - 8:20	///////,17,17,//////////	2
	8:20 - 8:25	50,////,15,17,/,18,/,25,///,31,28,////////	11
///,/P	8:25 - 8:30	19,////////,33,/,33,32,/,88	13
//P,/,	8:30 - 8:35	////,41,/,22,/,20,///,15,20,36,/,21	10
//P,/,/	8:35 - 8:40	22,/,13,////////,23,////////,20,/,15,////	5
	8:40 - 8:45	19,/,18,30,/,20,/,17,13,////////,22,////,15,/,	9

Afternoon Intervals

# of Peds	Time (PM)	Gaps Leg: <input type="checkbox"/> N <input type="checkbox"/> S <input checked="" type="checkbox"/> E <input type="checkbox"/> W	# of Gaps
	<Drop downs>		
/P,/,//P,//P,/,/P	3:05 - 3:10	/,30,////,15,16,/,26,30,///,18,/,	9
//,/P,/,/P,/,/	3:10 - 3:15	/,14,////////,15,/,26,////////,15,///,30,/,14,//	8
	3:15 - 3:20	///,30,////////,31,/,28,/,15,18,/,16,/,21	10
	3:20 - 3:25	38,/,14,31,14,22,42,41,/,62,/,33	19
	3:25 - 3:30	37,60,/,26,20,/,	9

Observations

Volume of Traffic:	AM: <input type="checkbox"/> Heavy <input checked="" type="checkbox"/> Intermittent <input checked="" type="checkbox"/> Light	PM: <input type="checkbox"/> Heavy <input checked="" type="checkbox"/> Intermittent <input checked="" type="checkbox"/> Light
Number of Crossing Pedestrians:	+ 3 AFTER SCHOOL ENTRY BELL	
	AM: North East 13 South West	PM: North East 17 South West
Turning Traffic:	AM: <input type="checkbox"/> Heavy <input type="checkbox"/> Intermittent <input type="checkbox"/> Light	PM: <input type="checkbox"/> Heavy <input type="checkbox"/> Intermittent <input type="checkbox"/> Light

Traffic Behaviour (Comment or Recommendation Required)

AM:	<input type="checkbox"/> Illegal U-turn	<input type="checkbox"/> Running Red Light	<input type="checkbox"/> Speeding	<input type="checkbox"/> Stopping Non-Compliance	<input type="checkbox"/> Illegal Stopping	<input type="checkbox"/> Illegal Parking	<input type="checkbox"/> Other
PM:	<input type="checkbox"/> Illegal U-turn	<input type="checkbox"/> Running Red Light	<input type="checkbox"/> Speeding	<input type="checkbox"/> Stopping Non-Compliance	<input type="checkbox"/> Illegal Stopping	<input type="checkbox"/> Illegal Parking	<input type="checkbox"/> Other

Comments/Conflicts Indicate the corresponding number(s) as well as additional comment(s)

- STUDENTS CROSSED MCBRIDE AVENUE - MOST ON THE DIAGONAL, TO GET TO EAST SIDE OF SCHOOL DRIVEWAY TO ACCESS THE SCHOOL.
- DRIVEWAY TRAFFIC COURTEOUS TO CROSSING PEDESTRIANS.
- TRAFFIC SCHOOL RELATED - EARLY AM TRAFFIC FOR WOODLANDS SENIOR PUBLIC SCHOOL PARKING AT LIBRARY ADJACENT TO MCBRIDE PUBLIC SCHOOL.
- NO CONFLICTS OBSERVED.
- AMPLE SAFE GAPS IN TRAFFIC FOR STUDENTS TO CROSS THE ROAD.
- NUMEROUS SAFE GAPS FOR STUDENTS TO CROSS. STUDENTS MINDFUL OF TRAFFIC BEFORE CROSSING.
- STUDENTS CROSS CONFIDENTLY.
- ALL SIGNAGE IN PLACE ON MCBRIDE AVENUE IN THE SCHOOL ZONE.

Recommendations Indicate the corresponding number(s) as well as location and/or school.

- 1) THAT THE WARRANTS HAVE NOT BEEN MET FOR THE PLACEMENT OF A SCHOOL CROSSING GUARD AT GRECHEN ROAD AND MCBRIDE AVENUE FOR THE STUDENTS OF MCBRIDE PUBLIC SCHOOL.

From: Sheelagh Duffin
Sent: 2023/05/09 7:07 PM
To: Peter Tecza <peter.tecza@mississauga.ca>
Subject: RE: Supporting Documentation for McBride PS.pdf

Thanks for the information, Peter. The recommendation going forward to the next MSTSAC meeting May 31 is that the warrants have not been met for the implementation of a crossing guard.

Most vehicles adhered to the speed limit during the school entry and dismissal times when MSTSAC was recording data. However, once school went in or dismissed and there were no students present a small number of vehicles were observed speeding. Traffic was very courteous and well-behaved at school entry and dismissal times.

Have a good evening!

Sheelagh



Sheelagh Duffin, BA
 Supervisor, Crossing Guards
 T [905-896-5167](tel:905-896-5167) | Fax [905-896-5166](tel:905-896-5166)
sheelagh.duffin@mississauga.ca

[City of Mississauga](#) | Transportation and Works
 Traffic Management and Municipal Parking
 3185 Mavis Road
 Mississauga ON L5C 1T7

From: Peter Tecza <peter.tecza@mississauga.ca>
Sent: 2023/05/09 5:52 PM
To: Sheelagh Duffin <Sheelagh.Duffin@mississauga.ca>
Cc: Max Gill <Max.Gill@mississauga.ca>; Milan Pavlovic <Milan.Pavlovic@mississauga.ca>
Subject: FW: Supporting Documentation for McBride PS.pdf

Hi Sheelagh,
 I apologise for the late reply. We have completed our studies early this year and the all-way stop condition was not warranted. See attached correspondence.
 As for any additional measures, we have installed supplementary speed limit signs on McBride Avenue. ASE was also deployed to McBride Avenue in the second half of 2022. Max's group is looking at additional measures such as speed awareness and potential bollards.

Peter

From: Sheelagh Duffin <Sheelagh.Duffin@mississauga.ca>
Sent: Wednesday, May 3, 2023 1:11 PM
To: Peter Tecza <peter.tecza@mississauga.ca>
Subject: Supporting Documentation for McBride PS.pdf

Hi Peter.

MSTSAC will be re-inspecting the intersection of McBride Avenue and Grechen Road Tuesday, May 9 to determine if the warrants are met for the implementation of a school crossing guard. The Site Inspection conducted in November, 2022 produced inconclusive results so MSTSAC recommended returning this Spring to have another look. I am wondering if any of the other requests from the email attached are being considered or have been implemented since the resident request October, 2022.

Thanks, Peter.

Sheelagh