

Appendix 5

**Ministry for Seniors and
Accessibility**

Accessibility for Ontarians with
Disabilities Division
AODA Compliance Operations
and Enforcement Unit

777 Bay Street, 6th Floor
Toronto ON M7A 2J4

**Ministère des Services aux aînés et de
l'Accessibilité**

Division de l'accessibilité pour les personnes
handicapées de l'Ontario
Unité des opérations de conformité et de
l'application de la LAPHO

777, rue Bay, 6^e étage
Toronto ON M7A 2J4



December 15, 2023

Ref #: P2 – 121414106

Dan Sadler
Accessibility Report Certifier
The Corporation of the City of Mississauga (121414106)
300 City Centre Drive
Mississauga ON L5B 3C1

Dear Dan Sadler:

**RE: INSPECTION UNDER THE ACCESSIBILITY FOR ONTARIANS WITH
DISABILITIES ACT, 2005**

A site inspection of **The Corporation of the City of Mississauga (121414106)** was conducted at multiple locations pursuant to the [Accessibility for Ontarians with Disabilities Act, 2005 \(AODA\)](#) on **September 27, 2023**.

The purpose of the on-site inspection was to assess compliance with certain requirements under O. Reg. 191/11, the AODA's Integrated Accessibility Standards Regulation (IASR).

Information was obtained from the on-site inspection based on observations, measurements and discussions with your organization's representatives. The inspection was limited to the selected requirements of the IASR referenced in the initial inspection notice (also noted in Appendix A).

The results of this inspection are set out in **Appendix A**.

Based on the inspection that was completed, we did not identify any instances of non-compliance. Please note that future inspections may examine the same matters with different points of emphasis or different methods of inspection, which may result in different findings. In addition, we may inspect other applicable requirements. This concludes our inspection, and no further action is required from you at this time.

This post inspection notice does not in any way provide assurance that your organization is in full compliance with the AODA and the IASR. Obligated organizations have a continuing obligation to ensure that they are compliance with any applicable requirements in the AODA and the IASR.

The Ministry also conducts desk audits and may select your organization for an audit in the future to confirm compliance with the AODA and the IASR.

Thank you for the co-operation extended to Ministry staff during the inspection. If you have any questions or concerns, please feel free to contact Agnieszka Dabrowska at: **Telephone: 437-833-0729** or E-mail: AODA.Inspections@ontario.ca.

Sincerely,

Rory Burke
 Director, Accessibility for Ontarians with Disabilities Act
 Accessibility for Ontarians with Disabilities Act Division
 Ministry for Seniors and Accessibility

We want to hear from you. How was my service? You can provide feedback at 1-888-745-8888 or ontario.ca/inspectionfeedback.

**Available in French and in alternate format upon request
 Disponible en français et, sur demande, dans un format alternatif**

Appendix A

DOPS	<u>80.9(1)</u>	Tech req. for trails, general - NA
	<u>80.10</u>	Tech req. for beach access routes, general – Assessed
	<u>80.12</u>	Boardwalks – Assessed
	<u>80.13</u>	Ramps – NA
	<u>80.23</u>	Exterior Paths of Travel, tech req. - Assessed
	<u>80.24(1)</u>	Exterior paths of travel, ramps – NA
	<u>80.25</u>	Exterior paths of travel, stairs - NA

	<u>80.26(1)</u>	Exterior paths of travel, curb ramps - NA
	<u>80.27(1)</u>	Exterior paths of travel, depressed curbs - Assessed