

# Site Inspection Report

Corporate Services  
Office of the City Clerk



## Site

School #1	St. Teresa of Avila Catholic Elementary School	Address	6675 Montevideo Road Mississauga, Ontario L5N 4E8	School Times	8:30 AM 3:00 PM
Student Population	386	French Immersion Population	45	No. of Large Buses	1
				No. of Small Buses	1
				No. of Students on the Bus	55
				No. of Students on the Bus	1
School #2		Address		School Times	AM PM
Student Population		French Immersion Population		No. of Large Buses	
				No. of Small Buses	
				No. of Students on the Bus	
				No. of Students on the Bus	
Location:	In Front of School on Montevideo Road @ Lake Aquitaine Trail				
Proximity to School	Name of School #1	St. Teresa of Avila Catholic Elementary School	in front of <input checked="" type="checkbox"/>	within	<input type="checkbox"/> feet <input type="checkbox"/> metres
	Name of School #2		in front of <input type="checkbox"/>	within	<input type="checkbox"/> feet <input type="checkbox"/> metres
Accident History (during school times)	Yes <input type="checkbox"/>	No <input type="checkbox"/>	Comments:		
Date of Inspection	2024	12	05	Inspection Time	AM 8:00 to 8:30 PM 3:00 to 3:30
Requested By	Parent via Councillor				
Prepared By	M. Roque		Request For	Implementation of a School Crossing Guard / Safety Measures	

## Observers

File Number	RT.10	File Number	RT.10	Ward	9
Observed By	AM	PM	Observed By	AM	PM
M. ROQUE	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>
M. GALESIC	<input type="checkbox"/>	<input checked="" type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>
	<input type="checkbox"/>	<input type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>
	<input type="checkbox"/>	<input type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>
	<input type="checkbox"/>	<input type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>

## Site Conditions

School Signs:	<input checked="" type="checkbox"/> School Area Signs	<input type="checkbox"/> School Crossing Signs	<input checked="" type="checkbox"/> Parking/Stopping Prohibition	<input checked="" type="checkbox"/> No U-turn Sign
Posted Speed Limit:	<input checked="" type="checkbox"/> 30 km/hr	<input type="checkbox"/> 40 km/hr	<input type="checkbox"/> 50 km/hr	<input type="checkbox"/> 60 km/hr
Other:				
Visibility of Crossing Pedestrians:	<input type="checkbox"/> Poor	<input type="checkbox"/> Fair	<input checked="" type="checkbox"/> Good	Comments:
Sight Obstructions:	<input type="checkbox"/> Hedges	<input checked="" type="checkbox"/> Trees	<input type="checkbox"/> Fences	<input type="checkbox"/> Bus Shelter
	<input type="checkbox"/> Newspaper Boxes	<input type="checkbox"/> Other (Specify)		
Road Grade:	<input checked="" type="checkbox"/> Flat	<input type="checkbox"/> Incline	<input type="checkbox"/> Decline	
Road Geometrics:	<input type="checkbox"/> Straight	<input checked="" type="checkbox"/> Curved	South	Comments:
Road Width/Street Name	Montevideo Road	Curb to Curb	No. of Bike Lanes	No. of Through Lanes
Leg: <input type="checkbox"/> N <input type="checkbox"/> S <input type="checkbox"/> E <input type="checkbox"/> W		Feet Metres		2
No. of Turning Lanes				
Road Width/Street Name		Curb to Curb:	No. of Bike Lanes	No. of Through Lanes
Leg: <input type="checkbox"/> N <input type="checkbox"/> S <input type="checkbox"/> E <input type="checkbox"/> W		Feet Metres		
No. of Turning Lanes				
Road Conditions:	AM: <input type="checkbox"/> Dry <input type="checkbox"/> Wet	PM: <input type="checkbox"/> Dry <input checked="" type="checkbox"/> Wet	<input checked="" type="checkbox"/> Snow Covered	<input checked="" type="checkbox"/> Ice
			<input type="checkbox"/> Snow Covered	<input type="checkbox"/> Ice
Sidewalks:	<input type="checkbox"/> Not Present	<input type="checkbox"/> North	<input checked="" type="checkbox"/> East	<input checked="" type="checkbox"/> West
Route Survey:	<input type="checkbox"/> Shopping Area	<input type="checkbox"/> Construction	<input type="checkbox"/> Driveway	<input type="checkbox"/> Parked Vehicle(s)
Within <input type="checkbox"/> Feet <input type="checkbox"/> Metres	<input type="checkbox"/> Transit Bus Stop	<input checked="" type="checkbox"/> Underpass	<input checked="" type="checkbox"/> Other (specify)	Residential
Traffic Calming:	<input checked="" type="checkbox"/> Speed Bumps	<input type="checkbox"/> Speed Cameras	<input checked="" type="checkbox"/> Crossover	<input type="checkbox"/> Other

## Details

Weather Conditions:		AM:	<input checked="" type="checkbox"/> Dry	<input type="checkbox"/> Sunny	<input type="checkbox"/> Rain	<input type="checkbox"/> Snow	Temperature	- 2 C	Other	Cloudy
		PM:	<input type="checkbox"/> Dry	<input checked="" type="checkbox"/> Sunny	<input type="checkbox"/> Rain	<input type="checkbox"/> Snow	Temperature	0 C	Other	
Type of Crossing:	<input type="checkbox"/> 4 Way Intersection	<input type="checkbox"/> 3 Way Intersection	<input checked="" type="checkbox"/> Midblock (i.e., not an intersection)							
Type of Control:	<input type="checkbox"/> Traffic Lights	<input type="checkbox"/> Yield Signs	<input checked="" type="checkbox"/> Pedestrian Crossover							
	<input type="checkbox"/> Stop Signs (Traffic is stopped on one street only)	<input type="checkbox"/> All Way Stop (Traffic is stopped in all directions)								

## Crossing Guard Warrant Survey

Location: <span style="border: 1px solid black; padding: 2px 10px;">In Front of School on Montevideo Road @ Lake Aquitaine Trail</span>	
<input checked="" type="checkbox"/> Safe Gap Time <input type="checkbox"/> Signalized Intersection Turning Traffic Count	Safe Gap Time Calculation (if applicable): $\left( \frac{W}{3.5} + 4 \right) = $ <span style="border: 1px solid black; padding: 2px 10px; display: inline-block; min-width: 150px;">14</span> seconds

## Morning Intervals

[illegible]

### Afternoon Intervals

[illegible]

**Observations**

Volume of Traffic:		AM: <input type="checkbox"/> Heavy <input checked="" type="checkbox"/> Intermittent <input type="checkbox"/> Light				PM: <input type="checkbox"/> Heavy <input checked="" type="checkbox"/> Intermittent <input type="checkbox"/> Light												
Number of Crossing Pedestrians:																		
AM: Midblock		29	North	<input type="checkbox"/>	East	<input type="checkbox"/>	South	<input type="checkbox"/>	West	PM: Midblock	63	North	<input type="checkbox"/>	East	<input type="checkbox"/>	South	<input type="checkbox"/>	West
Turning Traffic:		AM: <input type="checkbox"/> Heavy <input type="checkbox"/> Intermittent <input type="checkbox"/> Light				PM: <input type="checkbox"/> Heavy <input type="checkbox"/> Intermittent <input type="checkbox"/> Light												

**Traffic Behaviour** (Comment or Recommendation Required)

AM:	<input type="checkbox"/> Illegal U-turn	<input type="checkbox"/> Running Red Light	<input type="checkbox"/> Speeding	<input type="checkbox"/> Stopping Non-Compliance	<input type="checkbox"/> Illegal Stopping	<input type="checkbox"/> Illegal Parking	<input type="checkbox"/> Other	<input type="text"/>
PM:	<input type="checkbox"/> Illegal U-turn	<input type="checkbox"/> Running Red Light	<input type="checkbox"/> Speeding	<input type="checkbox"/> Stopping Non-Compliance	<input type="checkbox"/> Illegal Stopping	<input type="checkbox"/> Illegal Parking	<input type="checkbox"/> Other	<input type="text"/>

**Comments/Conflicts** Indicate the corresponding number(s) as well as additional comment(s)

<ul style="list-style-type: none"> <li>- no conflicts observed.</li> <li>- stopping compliance good when students present, poor when no students present.</li> <li>- ample safe gaps in traffic for students to cross the road.</li> <li>- students mindful of traffic before crossing. - students cross confidently.</li> <li>- not all students and parents are pushing the pedestrian button to call up the walk signal.</li> <li>- most students crossed with parents. - a few older students crossed on own.</li> <li>- significantly more students crossed in PM.</li> <li>- some u-turns, not enough to request enforcement.</li> <li>- traffic school related.</li> </ul>
---

**Recommendations** Indicate the corresponding number(s) as well as location and/or school.

<ol style="list-style-type: none"> <li>1) That the warrants have not been met for the placement of a school crossing guard at the pedestrian crossover in front of St. Teresa of Avila Catholic Elementary School.</li> <li>2) That Transportation &amp; Works be requested to:             <ol style="list-style-type: none"> <li>A) Replace the current PXO pedestrian information sign with the updated PXO pedestrian information sign (see attached).</li> <li>B) Review the painted crosswalk ladder markings to determine if they require re-painting.</li> </ol> </li> <li>3) That the principal of St. Teresa of Avila Catholic Elementary School be requested to share the PXO pedestrian information sign with students and parents in a school newsletter once installed, as a reminder to always push the pedestrian button and wait for vehicles to stop.</li> </ol>
--

# Pedestrian Crossover



**Push  
button  
to cross**



**Wait for  
traffic  
to stop**



**Make  
eye  
contact**



**Walk  
bicycle  
across road**

**Stay  
Alert**



**MISSISSAUGA**